












ECX-TF











1a








			
	W mm	H mm	X mm
ECX C02	600	900	479
ECX C04	600	1000	543
ECX F06	700	1400	606
ECX M04	800	1000	543
ECX M06	800	1200	606
ECX M08	800	1400	676
ECX P04	1000	1000	543
ECX P10	1000	1500	740
ECX S06	1200	1200	606
ECX U04	1400	1000	543
ECX U08	1400	1400	676
ECX U10	1400	1500	740



1b





			
	W mm	H mm	X mm
ECX C02	600	940	479
ECX C04	600	1150	543
ECX F06	700	1360	606
ECX M04	800	1150	543
ECX M06	800	1360	606
ECX M08	800	1590	676
ECX P04	1000	1150	543
ECX P10	1000	1810	740
ECX S06	1200	1360	606
ECX U04	1400	1150	543
ECX U08	1400	1590	676
ECX U10	1400	1810	740

1c





			
	W mm	H mm	X mm
ECX C02	600	900	479
ECX C04	600	1000	543
ECX F06	700	1400	606
ECX M04	800	1000	543
ECX M06	800	1200	606
ECX M08	800	1400	676
ECX P04	1000	1000	543
ECX P10	1000	1500	740
ECX S06	1200	1200	606
ECX U04	1400	1000	543
ECX U08	1400	1400	676
ECX U10	1400	1500	740




2




3






4






5








6








7






8







9









10





11






12







13



14



15



AR: VELUX Argentina S.A.
0 114 711 5666

AT: VELUX Österreich GmbH
02245/32 3 50

AU: VELUX Australia Pty. Ltd.
1300 859 856

BA: VELUX Bosna i Hercegovina d.o.o.
033/626 493, 626 494

BE: VELUX Belgium
(010) 42.09.09

BG: VELUX Bulgaria EOOD
02/955 95 26

BY: VELUX Roof Windows FE
(017) 217 7385

CA: VELUX Canada Inc.
1 800 88-VELUX (888-3589)

CH: VELUX Schweiz AG
0848 945 549

CL: VELUX Chile Limitada
2 953 6789

CN: VELUX (CHINA) CO. LTD.
0316-607 27 27

CZ: VELUX Česká republika, s.r.o.
531 015 511

DE: VELUX Deutschland GmbH
0180-333 33 99

DK: VELUX Danmark A/S
45 16 45 16

EE: VELUX Eesti OÜ
621 7790

ES: VELUX Spain, S.A.
91 509 71 00

FI: VELUX Suomi Oy
0207 290 800

FR: VELUX France
0821 02 15 15
0,119€ TTC/min

GB: VELUX Company Ltd.
0870 380 9593

HR: VELUX Hrvatska d.o.o.
01/5555 444

HU: VELUX Magyarország Kft.
(06/1) 436-0601

IE: VELUX Company Ltd.
1800 409 750

IT: VELUX Italia s.p.a.
045/6173666

JP: VELUX-Japan Ltd.
0570-00-8145

LT: VELUX Lietuva, UAB
(85) 270 91 01

LV: VELUX Latvia SIA
67 27 77 33

NL: VELUX Nederland B.V.
030 - 6 629 629

NO: VELUX Norge AS
22 51 06 00

NZ: VELUX New Zealand Ltd.
0800 650 445

PL: VELUX Polska Sp. z o.o.
(022) 33 77 000 / 33 77 070

PT: VELUX Portugal, Lda
21 880 00 60

RO: VELUX România S.R.L.
0-8008-83589

RS: VELUX Srbija d.o.o.
011 3670 468

RU: ZAO VELUX
(495) 737 75 20

SE: VELUX Svenska AB
042/20 83 80

SI: VELUX Slovenija d.o.o.
01 724 68 68

SK: VELUX Slovensko, s.r.o.
(02) 33 000 555

TR: VELUX Çatı Pencereleri
Ticaret Limited Şirketi
0 216 302 54 10

UA: VELUX Ukraina TOV
(044) 2916070

US: VELUX America Inc.
1-800-88-VELUX